

Criteria for disposal of slings and chain components



Overload deformation of the hook.



Marking is illegible. Missing.



Rusty sling components.



Worn latch, the hook does not close properly.



Protruding connection pin.



Deformation caused by overload.



Cuts, material loss, cracks.




Elongated chain links.



Welding lifting components is not allowed!



Visible chain wear.



Always lift safely!

